

CNC

Clamp

CNC


Clamp

to allow for rotation without contact with surrounding hardware.

3. Tension all hardware to manufacturers recommended torque settings.



Part Number	Torque
PFC13-14	7Nm
PFC15-16	7Nm
PFC17-18	10Nm
PFC19-20	10Nm
PFC21-22	10Nm
PFC23-24	10Nm
PFC25-27	10Nm
PFC28-30	10Nm
PFC31-33	10Nm





sales@powerflex.co.uk

POWERFLEX

www.powerflex.co.uk